




Eastern Point, Gloucester Average Salinity Pre and post restoration




Salinity vs. Presence of Phragmites Eastern Point, Gloucester 2000-2009




Average Salinity vs. Well Depth Eastern Point, Gloucester 2000-2009



Average Salinity Change vs. Depth for Transect 1, Eastern Point, Gloucester



Average Salinity vs. Pre and post restoration Transect 3, Eastern Point, Gloucester 2000-2001 vs. 2004-2008



Eastern Point Average Salinity by Year

